



# SOFTWARE RELEASE NOTES

---

## MCS-MICROMAG

## Version 4.00V

## 05/07/2013

### Updates from previous versions:

#### New Features:

1. Added Hood On. This will reset the mode enable sensors to the outdoor sensors.

#### Bug Fixes:

1. Ensured that when in cooling mode, demand was necessary before turning on one stage.
2. When the output of a capacity control does not change, left adjust delay at 0.
3. Only allowed cooling capacity control to shut off when either shutting off due enable, or due to low target temperature Cooling shutoff temp is either halfway between freeze setpoint and cooling target, or cooling target - 5 degrees.
4. Updated some Modbus addresses to coincide with Magnum.
5. Added an SI name.
6. Exhaust fan was staging on and off erratically when turned on then shut back off due to lowering static pressure. Resolution: Noticed missing code in capacity control algorithm that was causing exhaust fan to act erratically.

Any questions regarding this release, contact:

[support@mcscontrols.com](mailto:support@mcscontrols.com)

---

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905  
(239)694-0089 FAX: (239)694-0031 [www.mcscontrols.com](http://www.mcscontrols.com)

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2013. Copying or distributing this document is prohibited unless expressly approved by MCS.