



SOFTWARE RELEASE NOTES

MCS-MICROMAG

Version 4.00X

05/15/2013

Updates from previous versions:

Bug Fixes:

1. If the Network address was being changed, MicroMag would change its address in the middle of a configuration transmit. Resolution: The MicroMag will no longer change its network address in the middle of a config transmit.
2. Digital Scroll Voltages were being set to old digital scroll minimum voltages. Resolution: Set Digital Scroll Voltage to new Digital Scroll.

Any questions regarding this release, contact:

support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2013. Copying or distributing this document is prohibited unless expressly approved by MCS.