



SOFTWARE RELEASE NOTES

MCS-MICROMAG

Version 5.00A

05/20/2013

Updates from previous versions:

New Features:

1. Began work on chiller option
2. Implemented LLS RO

Bug Fixes:

1. When using the same sensor for mode enable and control target, use target setpoint rather than enable setpoint.

Any questions regarding this release, contact:

support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2013. Copying or distributing this document is prohibited unless expressly approved by MCS.